Reply to Pre-bid Queries

Tender No.:IGL/ET2/CP/CC17451 DISMANTLING, ERECTION, COMMISSIONING AND TRANSPORTATION OF CNG COMPRESSOR PACKAGES IN IGL GA's

Sr. No.	Clause No.	Page No.	Tender Clause	Bidder's Queries	Reply / Clarifications
1	1.4	59		Mobilization of team shall be 72 hrs instead of 48 hrs	Tender conditions shall prevail
2	1.7		The contractor shall arrange place for storing material. IGL will not provide any space for storing these items in CNG stations.	Place of storing of material at site shall be in IGL scope	Tender conditions shall prevail
3	1.16		II OMNTECCOT/BOOCIET/INTEGTATED PACKAGE AT A GIVEN NOINT	Deploy more than 2 teams at time-shall be maximum 02 teams at a time	Tender conditions shall prevail
4	2.4 b		Old recovered material during dismantling of compressor package at site should be re-used during commissioning of compressor package at other site.	Reuse of old material- reuse of material involves use of fresh material too such as elbow, socket, tee, welding etc which need funds. Hence some portion of measurement needs to be billed to IGL to compensate the cost.	Tender conditions shall prevail
5	SOR	SOR	L/ Brom SUTO 100	Range of kms <50, 50 to 100, 100 to 250 etc- If distance is 100 kms, in which range it shall fall?	Kms range should be read as follows 1). $0 < Kms \ Range \le 50$ 2). $50 < Kms \ Range \le 100$ 3). $100 < Kms \ Range \le 250$ 4). $250 < Kms \ Range \le 500$
6	SOR	SOR		One more category shall be there for distance more than 500 kms	Tender conditions shall prevail

Reply to Pre-bid Queries

Tender No.:IGL/ET2/CP/CC17451

DISMANTLING, ERECTION, COMMISSIONING AND TRANSPORTATION OF CNG COMPRESSOR PACKAGES IN IGL GA's

Sr. No	. Clause No.	Page No.	Tender Clause	Bidder's Queries	Reply / Clarifications
7	SOR	SOR	Supply, testing, transportation & erection of SS 304 tubing for air line of 2" OD along with required fittings and valves. Any additional/ special fitting to hook-up with the existing system shall be in the scope of contractor	2"Airline mentioned SS304, shall be MS or SS304	Refer Corrigendum - 2